

FITNESS CERTIFICATE

TO BE FILLED BY THE INSPECTING OFFICER

(ASSISTANT ENGINEER)

1 Name of the Officer

ELDO SIMON

2 Name of the School
,Kodakara

: Saraswathy Vidhya Nikethan Central School Perambra

3 Location with Name of Educational

District Sub District

: Chalakudy Sub Dist. Irinjalakuda Dist.

4 Classification buildings as specified in Col. 4

: Main Block

Of the application for fitness certificate & Size

: 600*600(6- class rooms) GF

: 600*600 (1- Staff room, 1- Director Board room)

: 600*600 (6- class rooms) FF

: 600*600 (Staff room, Computer Lab-FF)

: 1456*600 (Library)

: 600*600 (7- Class room) SF

: 600*600 (3- No Labs-SF)

Main Block Total Area = 2602 M2

Vivekanadha Block

: 600*600 (8- class rooms)

: 440*600 (Staff room-GF, FF & SF)

Total Area- 1635.30 M2

5 Period For which the certificate is issued

: 2025-26

6 Nature of Defect if any

a) Foundation and Basement

: Good Condition

b) Super Structure

: Good Condition

c) Doors and Windows

: Good Condition

d) Wood Work Wrought put up

: Nil.

- e) Roof : Good Condition
f) Flooring : Good Condition
g) Miscellaneous cracks etc : Cracks on two classes

7 Any major defects noticed which will render
The building unsafe if any manner : No

8 Whether the maintenance works have been
Done properly : Yes

9 Whether structure is safe for conducting classes : Sound fit under normal wind and weather conditions.

Note : Advice to carry out water proofing works to avoid the dampness in the roof slab.
Stair Room to be locked

CERTIFICATE

Certified that the school building was inspected by me on **29-06-2025** and found to be fit/~~unfit~~ to conduct classes, for the period **2025-26** for the reasons stated.

Place : Kodakara
Date : 30-06-2025

(Seal)



Assistant Engineer

ELDO SIMON
PEN: 859565
ASSISTANT ENGINEER
LSGD - LID&EW SECTION
KODAKARA